




AWA501


WIRING DIAGRAM

230 VAC
SINGLE PHASE
60 HZ




WIRING DIAGRAMS POWER/PUMP CONNECTIONS: AWA501/AWA502/AWA503


POWER CONNECTION 230 VOLT AWA501, AWA502




AWA503




OPTIONAL CENTRIPRO CONTROL BOX AND PUMPSAVER WITH AWA501 AND AWA502 ONLY



POWER CONNECTION AWA501 115 VOLT



FIELD CONNECTIONS: AWA501, AWA502, AWA503



WARNING! Electric shock hazard. Open all remote disconnects before servicing this equipment.

Xylem Inc.

2881 East Bayard Street Ext., Suite A, Seneca Falls, NY 13148

Phone: (866) 325-4210 Fax: (888) 322-5877

www.centripro.com

CentriPro is a trademark of Xylem Inc. or one of its subsidiaries.

© 2018 Xylem Inc. BCPAWA501 February 2018



CentriPro
a xylem brand